certification

FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1097

This is a product certificate to certify that

Humphrey & Stretton plc

Pindar Road, Hoddesdon, Hertfordshire, **EN11 0EU** +44 (0)1992 462965

who fabricate the following timber fire doors:

Strebord FD30 & FD60 Flamebreak FD30 & FD60 Egger FD30 Halspan FD30 & FD60 Moralt FD30 & FD60

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to BS476: Part 22, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from 30 minutes to 60 minutes integrity are detailed on page 2 of this certificate.



First Issued: 19th September 2014 Re-issued: 15th November 2019 Valid to: 18th September 2024

Issue No: 7



175

Ian Woodhouse Director of Certification

IFC Certification Ltd

20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com

Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.



Certificate number: IFCC 1097

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
Egger Eurospan	FD30	Chilt/A13085 A
Halspan Prima	FD30	06166B (HS01)
Halspan Prima	FD60	06167C (HS02)
Halspan Optima	FD30	PAR/10341/01 Rev A
		(HS03)
Halspan Optima	FD60	PAR/10341/02 Rev B
		(HS04)
Strebord 44	FD30	Chilt/A02066
Strebord 54	FD60	Chilt/A02067
Flamebreak 30	FD30	FEA/F98164 Rev L
Flamebreak 60	FD60	Chilt/A02141 Rev I
Moralt Laminesse Klassik &	FD30	PAR/14247/01
FireSmoke		
Moralt Laminesse	FD30	PAR/12519/01 Rev D
FireSmoke & FireSafe		
Moralt Laminesse	FD60	PAR/12519/02 Rev D
FireSmoke & FireSafe		
Moralt Laminesse	FD30 & FD60	PAR/14559/01
FireSound		
Moralt Laminesse	FD30 & FD60	PAR/12519/03 Rev E
FireSound		

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.